
WRAP Survey Zones
5 0 5
Miles
Hwy 3 to Trinity Center
Trinity Center to Stuart Creek
Stuart Creek to Trinity Sub
Trinity Substation
Trinity Sub to N. Lewiston
WAPA Line
Lewiston Substation
Lewiston
Buckhorn Summit
Weaverville
Weaverville
E/N Fork Trinity River & Canyon Creek
Junction City
Mill Street Substation
North of Indian Creek Lodge
Douglas City Substation
Indian Creek Lodge - Douglas City, Hwy 3
East Hayfork
Hayfork
Hayfork Substation
South Hayfork
Big Bar
Big Bar Substation
Grouse Creek Substation
Hyampom Surroundings
Forest Glen
Forest Glen Substation
299
3
36